



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3495025-074-2025

MDE OFFICIAL CONTACTED: EVELYN STAVROU

DATA CALLED IN BY: ROBIN DESPANZA

DATE: 08/27/2025 AT 11:36AM

WORK ORDER(S): 3495025 3494232

EST DATE AND TIME SSO BEGAN: 08/26/2025 02:56PM DURATION: 2.45 HRS

DATE AND TIME SSO ENDED: 08/26/2025 05:23PM

SOURCE-CONTRACTOR SS05101013 WATER BODY AFFECTED-ROCK CREEK

CLOSEST STREET ADDRESS: 12101-513 VILL SQ TER 20852

COUNTY/PAGE/GRID: M 5285 C01 TOWN/CITY: ROCKVILLE

CAUSE: DEFECTIVE MATERIAL EST OVERFLOW VOLUME: 4,410 GAL

UPON ARRIVAL, THE CREW FOUND THAT A SECTION OF BYPASS HOSE HAD SEPARATED, CAUSING APPROXIMATELY 30 GPM OF LIQUID SEWAGE TO ENTER INTO A NEARBY CREEK IN THE ROCK CREEK BASIN. A WSSC CONTRACTOR RECONNECTED THE HOSE, TO END THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER

NOTICEABLE ODOR

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

WSSC CONTRACTOR RECONNECTED THE HOSE. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

LIME

LIME WAS SPREAD IN THE AFFECTED AREA.

NOTIFICATIONS MADE:

MD DEPARTMENT OF ENVIRONMENT
DEP-MONTGOMERY COUNTY

MONTGOMERY CO MUNICIPALITIES

ORIGINALLY REPORTED AS 12507 VILLAGE SQUARE TER.

SIGNS POSTED: 25 POST DATE: 08/27/2025