



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3483192-109-2025

MOE OFFICIAL CONTACTED: CHRISTI WAGNER

DATA CALLED IN BY: 4581

DATE: 07/03/2025 AT 01:00PM

WORK ORDER(S): 3483192 3483182

EST DATE AND TIME SSO BEGAN: 07/03/2025 01:08PM DURATION: 9.37 HRS
DATE AND TIME SSO ENDED: 07/03/2025 10:30PM

SOURCE-REPAIR SEWER MAIN SS07074010 WATER BODY AFFECTED-CABIN JOHN

CLOSEST STREET ADDRESS: 11056 POWDER HORN DR 20854
COUNTY/PAGE/GRID: M 5284 B05 TOWN/CITY: POTOMAC

CAUSE: UNKNOWN EST OVERFLOW VOLUME: 562 GAL
UPON ARRIVAL, THE CREW FOUND DISCHARGE COMING FROM A SECTION OF BROKEN
PIPE IN SEWER SEGMENT 07074010, AND INTO BUCK BRANCH CREEK. THE CREW
INVESTIGATED AND FOUND NO MANHOLE OVERFLOWING. A CONTRACTOR SET UP
BYPASS PUMPS FROM MANHOLE 010M TO MANHOLE 003U, TO END THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:
DRY WEATHER DISCOLORATION
PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:
THE CONTRACTORS ARE SET TO REPAIR THE PIPE. A FOLLOW-UP INVESTIGATION
WILL BE CONDUCTED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO
REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

NOTIFICATIONS MADE:
MD DEPARTMENT OF ENVIRONMENT DEF-MONTGOMERY COUNTY
MONTGOMERY CO MUNICIPALITIES

SIGNS POSTED: 4 POST DATE: 07/03/2025